

### Cutting Speeds

| Material              | HSS          | Carbide      |
|-----------------------|--------------|--------------|
| Carbon Steel          | 80-100 SFPM  | 300-400 SFPM |
| Alloy Steel           | 40-80 SFPM   | 200-300 SFPM |
| Tool Steels           | 40-60 SFPM   | 160-200 SFPM |
| Aluminum Alloys       | 250-400 SFPM | 300-600 SFPM |
| Brass, Bronze, Copper | 200-300 SFPM | 360-400 SFPM |
| Cast Iron             | 70-90 SFPM   | 250-300 SFPM |

### Drilling Feed Rates

| Drill Size | IPR         |
|------------|-------------|
| .125/.250  | 0.002/0.004 |
| .250/.500  | 0.004/0.007 |
| .500/1.000 | 0.007/0.015 |

### Chip Load FPT

| Material        | End Mill $\varnothing$ |       |       |       |       |
|-----------------|------------------------|-------|-------|-------|-------|
|                 | 1/4                    | 3/8   | 1/2   | 3/4   | 1     |
| Carbon Steel    | 0.001                  | 0.002 | 0.003 | 0.004 | 0.006 |
| Alloy Steel     | 0.001                  | 0.002 | 0.003 | 0.004 | 0.006 |
| Aluminum Alloys | 0.002                  | 0.003 | 0.005 | 0.008 | 0.010 |
| Brass & Bronze  | 0.002                  | 0.003 | 0.005 | 0.008 | 0.010 |
| Cast Iron       | 0.001                  | 0.002 | 0.003 | 0.004 | 0.006 |

**RPM** =  $3.82 \times \text{SFPM} / \text{Diameter}$

**Feed Rate (Milling IPM)** =  $\text{RPM} \times \text{FPT} \times \# \text{ of teeth}$

**Feed Rate (Drilling IPM)** =  $\text{RPM} \times \text{IPR}$

**Feed Rate (Lathe)** = IPR

**Drill Point Depth** =  $.3(118) \times \text{Drill Diameter}$

**Extra Drill Depth for Blind Tapping** =  $\text{Pitch} \times 9$

**Tapping FR** =  $\text{TPI} / \text{RPM}$

**Chamfer Depth** =  $\text{Drill Diameter} + \text{Chamfer Amount} \times \text{Chamfer Angle (example .5 for } 90^\circ \text{)}$

**Reaming** =  $\text{Drill Speed} / 2 \times \text{Drill Feed} \times 2$

**Inches to mm** =  $1'' = 25.4\text{mm}$

**MM to inches** =  $1\text{mm} = .03937''$

**Pipe Taps** = 4-5 Threads from end of tap

**Bridgeport Trimming** = Side to side (x) half, back and forth (y) double

**Lathe Feed** =  $.010''/\text{rev}$  for most turning

**Endmill Plunge rate** =  $\frac{1}{4}$  of normal federate

### Chamfer Angle Chart

| Angle       | Amount | Angle       | Amount |
|-------------|--------|-------------|--------|
| $60^\circ$  | 0.866  | $82^\circ$  | 0.575  |
| $90^\circ$  | 0.500  | $118^\circ$ | 0.300  |
| $120^\circ$ | 0.288  | $135^\circ$ | 0.207  |